

Campton Ranch – c. 1890 Fortuna, CA



West elevation – Through time, additions change the original footprint.




Window restoration



Southeast elevation – Most windows, including entry sidelights need re-glazing.

Current HPRT project.

In Fall 2000, the ranch was offered to use as a classroom lab. Students are in the process of weatherization strategies and historical research to develop a preservation plan.



Roof/wall flashing installation and weatherization



Room 102 – Fireplace hearth footing is river rubble



Room 103 – Kitchen tells a story