



Senior Resource Center, Eureka - Fall 1999
College of the Redwoods HPRT Students
Balustrade reconstruction project

Reproducing balusters from rotted originals



Trimming new balustrade to fit between reconstructed newel posts



Repairing existing newel post for reconstruction



Installing new balustrade – another job completed

